


37023404

SECTION CORNER - DATA SHEET

| | | | |
|--|--|--|----------------------|
| PROJECT NAME | JOB No.: ST. JOSEPH COUNTY GPS | STATION NUMBER: 755 - | STATION NAME: |
| DEGREES, MINUTES, SECONDS | | STATE PLANE COORDINATE SYSTEM OF 1983 BASED ON NORTH AMERICAN DATUM OF 1983 | |
| LATITUDE: 41°39'05.50821" N | | NORTH: 2351006.793 | |
| LONGITUDE: 86°11'47.10586" W | | EAST: 154244.040 | |
| ELEVATION GEOID Ht. ELLIPSOID Ht. | CONVERGENCE: | | |
| ELEVATION + GEOID Ht. = HEIGHT | SCALE FACTOR: 0.999969269 | | |
| | ELEVATION FACTOR: | | |

SKETCH:



SURVEYOR'S REPORT: A RESEARCH OF RECORDS IN THE COUNTY SURVEYOR'S OFFICE AND THE OFFICE OF LANG, FEENEY & ASSOCIATES, INC. REVEALED NO EVIDENCE OF THE CORNER BEING PREVIOUSLY ESTABLISHED. THE OFFICE OF LANG, FEENEY & ASSOCIATES, INC. SURVEYED THE ENTIRE SECTION 33 TO BISECT OPPOSITE QUARTERS TO LOOK FOR PHYSICAL EVIDENCE AT THE LOCATION. THE CALCULATED LOCATION OF THE CENTER OF THE SECTION FELL ON AN ASPHALT PATCH IN THE CONCRETE PAVEMENT. REMOVAL OF THE PATCH EXPOSED A ONE INCH BRASS PLUG, ONE INCH BELOW THE CONCRETE SURFACE GRADE.

Terance D. Lang
TERANCE D. LANG, RLS No. S-0523



| | | |
|----------------------------|-------------------|--------------------------------------|
| STATE: INDIANA | ZONE: EAST | R. 2E ., T. 38 N., SECTION 33 |
| DATE: NOVEMBER 2008 | | CENTER OF SECTION |

by: **Lang - Feeney and Associates, Inc.**